



Warranty Repair Time Guidelines

REPAIR ITEM / DESCRIPTION	APPROVED REPAIR TIME	ADMINISTRATIVE / DIAGNOSTIC TIME
Replace Jack Leg (Straight Leg System): Remove leg, bolt on new leg.	35 min.	15 min.
Replace Jack Leg (Folding Leg System): Remove leg, bolt on new leg.	35 min.	15 min.
Replace Control Unit: Remove old controller, install new controller, attach wiring.	20 min.	15 min.
Replace Touch Pad: Remove old touch pad install new touch pad, attach wiring.	15 min.	15 min.
Replace Folding Gear Motor: Remove leg, remove small gear motor and replace with new motor. Reattach leg, connect wiring.	45 min.	15 min.
Test and recalibrate system. Paid once per repair authorization ticket.	10 min.	5 min.

Bullseye Technologies, Inc. will pay an established labor rate of \$95 per hour based on time guidelines stated above to all authorized service/repair facilities. Bullseye Technologies, Inc. will offer no reimbursement to individual coach owners for repairs they attempt themselves and there will no warranty on replaced products not installed by a certified service/repair facility.

Any claims for labor reimbursement above the established time guidelines must have prior written approval from Bullseye Technologies, Inc. Please contact the technical service department at 1-574-721-0228 for any questions regarding this policy.